

	Type	Hits	DBs	Time Stamp	Search Text	Comments	Error Definition
1	IS&R	35	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/04/24 09:55	("20030066976") or ("20020130278") or ("6534775") or ("6489622") or ("6326631") or ("6111260") or ("6039847") or ("5925886") or ("5780863") or ("5780862") or ("5748360") or ("5420437") or ("5365070") or ("4933551") or ("62147643") or ("6326631")		
2	BRS	99784	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/04/24 09:57	(250/\$7). ccls.		
3	BRS	274091	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/04/24 15:46	(beam\$1 source ray \$1 implan \$8) same (ions\$8 plasma)		Truncation overflow.
4	BRS	54330	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/04/24 09:57	(315/\$7). ccls.		
5	BRS	59737	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/04/24 10:02	accelerat \$3 and decelerat \$3		

	Type	Hits	DBs	Time Stamp	Search Text	Comments	Error Definition
6	BRS	678	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/04/24 10:57	((250/\$7) .ccls.) and ((beam\$1 source ra y\$1 impla n\$8) same (ion\$8 pl asma)) and (accelera t\$3 and decelerat \$3)		